	Тур	L #	Hits	Search Text	DBs	Time Stamp	Comments	Errord Hinition	Er ro rs
11	BRS	L11	1			2002/09/2 3 14:27			0
12	BRS	L12	4	123/184.21 and (pressure adj control adj valve)	USPA T; US-P GPUB	2002/09/2 3 14:27			0

	Тур	L #	Hit s	Search Text	DBs	Time Stamp	Соннептя	III	Er ro rs
1	BRS	L4	14	123/184.61 and (pressure same control same valve)	US-P GPUB	2002/09/2 3 14:26			0
2	BRS	L3	7	123/184.57 and (pressure same control same valve)		2002/09/2 3 13:54			0
3	BRS	L1	37	123/184.21 and (pressure same control same valve)		2002/09/2 3 13:56			0
4	BRS	L2	51	123/184.53 and (pressure same control same valve)	USPA T; US-P GPUB	2002/09/2 3 14:25			0
5	BRS	L5	118	123/572 and (pressure same control same valve)	USPA T; US-P GPUB	2002/09/2 3 14:25			0
6	BRS	L6	98	123/574 and (pressure same control same valve)	USPA T; US-P GPUB	2002/09/2 3 14:26			0
7	BRS	L7	8	123/574 and (pressure adj control adj valve)	USPA T; US-P GPUB	2002/09/2 3 14:26			0
8	BRS	L8	14	123/572 and (pressure adj control adj valve)	USPA T; US-P GPUB	2002/09/2 3 14:26			0
9	BRS	L9	1	123/184.61 and (pressure adj control adj valve)	USPA T; US-P GPUB	2002/09/2 3 14:27			0
10	BRS	L10	1	123/184.57 and (pressure adj control adj valve)	USPA T; US-P GPUB	2002/09/2 3 14:27			0

	Тур	L #	Hits	Search Text	DBs	Time Stamp	Comments	Errord finition	Errors
1	BRS	L1	11	(variable adj valve) same actuation same motor	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2002/09/2 3 12:24			0
2	BRS	L2	0	123/90.11 and ((variable adj valve) same actuation same motor)	USPA T; US-P GPUB	2002/09/2 3 12:25			0
3	BRS	L5	0	123/90.22 and ((variable adj valve) same actuation same motor)	USPA T; US-P GPUB	2002/09/2 3 12:25			0
4	BRS	L6	2	123/90.31 and ((variable adj valve) same actuation same motor)	;	2002/09/2 3 12:25			0
5	BRS	L4	1	123/90.16 and ((variable adj valve) same actuation same motor)		2002/09/2 3 12:26		***************************************	0
6	BRS	<b>L</b> 3	3	123/90.15 and ((variable adj valve) same actuation same motor)	USPA T; US-P GPUB	2002/09/2 3 12:26			0